
BOS Channel - Installation Instructions

Models BOSC-XX


Please read all instructions prior to installation and keep for future reference!


1. Product to be installed by a qualified electrician.

- 2. Prior to installation ensure power is off at fuse box to prevent electrical shock.
- 3. Fixture should be installed by two people.





1.1 Snap lens into the extrusion, then align & center the extrusion to the determined location. Make all necessary markings to install to the surface. Prior to installation of extrusion, 24VDC power must be present.





2.1 If necessary extrusion, lens, & mounting channel (if applicable) can be cut in the field. Snap all parts together then using the proper blade for aluminum cut to the desired length.







Page 1 of 2 7777 Merrimac Ave Niles, IL 60714 T 224.333.6033 F 224.757.7557 info@luminii.com www.luminii.com

BOS Channel - Installation Instructions

Models BOSC-XX

Please read all instructions prior to installation and keep for future reference!

Product to be installed by a qualified electrician.


- Prior to installation ensure power is off at fuse box to prevent electrical shock.
 Fixture should be installed by two people.

7777 Merrimac Ave Niles, IL 60714 T 224.333.6033 F 224.757.7557

info@luminii.com

Iuminii





mounting channel to secure in place.

7.1b If using a magnetic bracket, place onto a metal surface.

any remaining brackets.

